

300,000 Gallon Steel Standpipe Tank "Water Tank #2" City of Gonzales Gonzales, Texas

Observation No. 006 January 21, 2020

1. Roof rigging coupling.



2. Shell ladder installed.



Observation No. 007 January 23, 2020

Shell manhole cover davit arm.



Observation No. 008 January 24, 2020

Interior floor bracket removed.



4. Floor area ground.



5. Interior shell angle brackets removed and ground.



Observation No. 010 January 27, 2020

5. Exterior shell manhole cover lifting handles installed.



Observation No. 011 January 28, 2020

7. Interior abrasive on site.



300,000 Gallon Steel Standpipe Tank "Water Tank #2" City of Gonzales Gonzales, Texas

Observation No. 012 January 29, 2020

1. Generator on site.



2. Dust collector on site.



. Dehumidification unit on site.



Observation No. 013 January 30, 2020

4. Exterior roof safety railing toe bars installed.



5. Exterior roof manhole cover with padlock brackets installed.



Observation No. 014 January 31, 2020

6. Surface preparation meets SSPC-SP 10.



7. Surface preparation meets SSPC-SP 10.



Observation No. 015 February 1, 2020

8. Weir box ready to install.




Observation No. 016 February 2, 2020

9. Surface preparation meets SSPC-SP 10 modified.



10. Surface preparation meets SSPC-SP 10 modified.



Observation No. 017 February 3, 2020

11. Prime Coat.



12. Prime coat.



13. Exterior roof outriggers installed.



14. Interior weir box installed.



15. Interior weir box installed.



16. Exterior roof hole welded.



300,000 Gallon Steel Standpipe Tank "Water Tank #2" City of Gonzales Gonzales, Texas

Observation No. 020 February 6, 2020


1. Surface preparation meets SSPC-SP 10 modified.




2. Surface preparation meets SSPC-SP 10 modified.



3. Surface preparation meets SSPC-SP 10 modified.



4. Surface preparation meets SSPC-SP 10 modified.



Observation No. 021 February 7, 2020

5. Roof patch plate installed.



6. Roof patch plate installed.



7. Roof patch plate installed.



Roof patch plate installed.



9. Roof patch plate installed.



10. Dust collector.